

Work Order ID 66622



Page 1

Wednesday, February 23, 2011 8:07:23 AM

Item ID:	D350-591-312	Accept		Setup	Start	
Revision ID:					Stop	
Item Name:	Heli-Access-Step, Long RH					
Start Date:	2/23/2011	Start Qty:	10.00	Cust Item ID:		
Required Date:	3/18/2011	Req'd Qty:	10.00	Customer:		
Reference:						

Approvals:	Process Plan:		Date:	1-02-23	Tooling:		Date:		Run	Start	
	QC:		Date:		SPC (Y/N):		Date:			Stop	

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr								
D3272	Rev B								

100		0.00							
	DOCUMENT CONTROL								
DC	Memo	0.00							
Document Control	Photocopy bluefile and type labels as per PPP D350-591-312 CHG001								

Sulostz

JJ BG 11-3-21

110		0.00							
	Large Fab								
Large Fab	Memo	0.00							
Large Fab	1-Bevel end for welding FWD ONLY								
	2-Weld Support using Jig DT8719, weld Fwd End Plate as per QSI 004 & Dwg D3272								
	A/R Aluminum Rod <i>M108436</i>								
	3-Grind End Plate flush <i>M115928</i>								

11-03-10

10

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 66622

Wednesday, February 23, 2011 8:07:23 AM

Page 2

Item ID: D350-591-312

Accept

Revision ID:

Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011 Start Qty: 10.00

Required Date: 3/18/2011 Req'd Qty: 10.00

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

120



QC

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00

10

E

2/23/11

130



QC

Quality Control

QC5- Inspect part completeness to step on W/O

0.00

Memo

0.00

S1105117

210

RH

140



HandFinish

Hand Finishing

Chemical Conversion Coat per QSI005 4.1

0.00

Memo

0.00

11-03-11

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 66622

Page 3

Wednesday, February 23, 2011 8:07:23 AM

Item ID: D350-591-312

Accept



Setup Start



Revision ID:

Stop



Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011 Start Qty: 10.00



Cust Item ID:

Required Date: 3/18/2011 Req'd Qty: 10.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

150

QC3- Inspect Part Finish

0.00

11.03.15

10



QC

Memo

0.00

Quality Control

180

Large Fab

0.00

10



Large Fab

Memo

0.00

Large Fab

1-Assemble Leg Assembly as per Dwg D3272.

11.03.16

2-Leave one rivet out until welding is complete.

3-Bevel Aft end for welding

4-Inspect for foreign object as per QSI 024

5-Weld Aft End Plate as per QSI 004 & Dwg D3272
A/R ☐ Aluminum Rod ☒ M108436

6-Grind End Plate flush

7-Install last rivet as per Dwg.

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 66622

Wednesday, February 23, 2011 8:07:23 AM

Page 4

Item ID: D350-591-312

Accept

Setup Start

Revision ID:

Stop

Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011 Start Qty: 10.00

Cust Item ID:

Required Date: 3/18/2011 Req'd Qty: 10.00

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start

QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

190

QC10- Inspect visual per QSI004- ground welds

0.00



QC

Memo

0.00

Quality Control

10

0

2/23/17

200

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

2/23/17

710
R4

210

Chemical Conversion Coat per QSI005 4.1

0.00



HandFinish

Memo

0.00

Hand Finishing

10 BL 11-3-17

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

00000000000000000000000000000000

Page 5

**Setup Start**

Abstract

Stop

1. The first step in the process is to identify the problem. This involves gathering information about the situation and the people involved.

[REDACTED]

Customer:

Reference:

Run Start

Stop

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Abstract

**Insp.
Stamp**

0,00



Powdercoat

M115951

0.00

Powder Coating

Memo

START TIME: 11:15

OVEN TEMPERATURE:

FINISH TIME: 11:45

Wing Walk as per dwg QSI005 4.4 Batch



HandFinish

Memo

0.00

Hand Finishing

QC3- Inspect Part Finish

0.00



QC

Memo

0.00

Quality Control

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 66622

Wednesday, February 23, 2011 8:07:23 AM

Page 6

Item ID: D350-591-312

Accept

Setup Start

Revision ID:

Stop

Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011 Start Qty: 10.00

Cust Item ID:

Required Date: 3/18/2011 Req'd Qty: 10.00

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

250

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

11/3/21

100

260

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

8 u103/23

NO
RH

270

Packaging

0.00



Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPPD350-591-312
Location: _____

64/3/22 10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____








NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries

Work Order ID 66622

Wednesday, February 23, 2011 8:07:23 AM

Page 7

Item ID:	D350-591-312	Accept		Setup	Start	
Revision ID:					Stop	
Item Name:	Heli-Access-Step, Long RH					
Start Date:	2/23/2011	Start Qty:	10.00		Cust Item ID:	
Required Date:	3/18/2011	Req'd Qty:	10.00		Customer:	
Reference:						
Approvals:	Process Plan:	Date:	Tooling:	Date:	Run	Start
	QC:	Date:	SPC (Y/N):	Date:		Stop
						
						

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
280	QC21- Final Inspection - Work Order Release	0.00							
									
QC	Memo	0.00							
Quality Control									

11-03-23
10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, February 23, 2011 8:07:29 AM

Page 1

Work Order ID: 66622

Parent Item: D350-591-312

Parent Item Name: Heli-Access-Step, Long RH





Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP Rev:A 04.03.22 New issue KJ/RF
 IPP Rev:B 07-06-09 Added D3572-1 JLM
 IPP Rev:C 08-04-02 ECN1163 DD verified by:EC
 IPP Rev:D 08-04-08 ECN1164 DD verified by:cC IPP Rev:D
 fixe route seq in bom DD 10.04.28 verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3272-1 		Manufactured	No			110	Each	0.0000	1	10			
Step													
D3067-1 		Manufactured	No			110	Each	128.0000	1	10			
End Plate													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				WA		128				10			
				65969		128							
D3219-1 		Manufactured	No			110	Each	135.0000	2	20			
Plate													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				WA		135							
				63551		19				20			
				66133		116							
D3066-1 		Manufactured	No			180	Each	6.0000	2	20			
Spacer													
				<u>Location</u>		<u>Loc Qty</u>		<u>Loc Code</u>					
				WA		6				14			
				65072		6				6			

11.03.08 B66623

11.03.09

10
20
11.03.09

20
20
11.03.15

14
6

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, February 23, 2011 8:07:29 AM

Work Order ID: 66622



Parent Item: D350-591-312



Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

MS20600-AD4W4

Purchased

No

180

Each

2,263.000

16

160



11.03.15

Rivets

Location

Loc Qty

Loc Code

ST321

2263

113368

38

114181

11

114718

2

115573

70

115640

31

116022

4

116188

1500

116712

607

160

D3065-041

Manufactured

No

180

Each

57.0000

1

10



11.03.15

Step Leg Assembly Hi

Location

Loc Qty

Loc Code

WA

57

63554

17

66149

40

10

D3067-1

Manufactured

No

180

Each

128.0000

1

10



11.03.15

End Plate

Location

Loc Qty

Loc Code

WA

128

65969

128

10

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, February 23, 2011 8:07:30 AM

Page 3

Work Order ID: 66622

Parent Item: D350-591-312

Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

AN3-35A

Purchased No

250

Each

102.0000

2 20

Bolt

Location

Loc Qty

Loc Code

ST353

102

116191

100

116704

2

Manufactured No

250

Each

0.0000

2 20

Mounting Lug

D3278-041

Manufactured No

250

Each

1.0000

1 10

Support Assembly

Location

Loc Qty

Loc Code

ST471

1

63553

1

Purchased No

250

Each

30.0000

16 160

AN960JD416

NAS1149D0463J

Washer

Location

Loc Qty

Loc Code

ST300

24

113288

24

ST356

6

115622

6

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, February 23, 2011 8:07:30 AM

Page 4

Work Order ID: 66622

Parent Item: D350-591-312

Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

AN960JD516

NAS1149D0563J

Purchased

No

250

Each

34.0000



Washer

Location

Loc Qty

Loc Code

ST	34
103694	18
107534	12
109287	4

AN5-36A

Purchased

No

250

Each

157.0000



Bolt

Location

Loc Qty

Loc Code

ST34I	157
114292	1
116191	6
116549	50
116704	100

D2618

Manufactured

No

250

Each

83.0000



Bushing

Location

Loc Qty

Loc Code

ST019	83
65071	3
66132	80

4 40 39
M116540

11/3/215

2 20
11/3/215

2 20
11/3/215

100

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, February 23, 2011 8:07:30 AM

Page 5

Work Order ID: 66622

Parent Item: D350-591-312

Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

D2230-3

Manufactured No

250

Each

6.0000

Lug

Location

Loc Qty

Loc Code

Return 2010

4

62927

2

63544

2

ST476

2

55452

2

D2856-400

Manufactured No

250

f

188.3980

1.2

Abraison Strip

Location

Loc Qty

Loc Code

ST403

188.3980421

56626

0.00004211

59920

43.381

63735

145.017

cut (2) D2856-400-720 as per dwg

MS21042L3

Purchased No

250

Each

2,704.000

Nut

Location

Loc Qty

Loc Code

ST300

2704

110844

4

114784

9

115835

191

116391

900

116540

800

116549

800

Wednesday, February 23, 2011 8:07:30 AM

Shop Packet Print

Page 5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 6

Wednesday, February 23, 2011 8:07:31 AM

Work Order ID: 66622

Parent Item: D350-591-312

Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

AN4-13A

Purchased

No

250

Each

486.0000

8 80



Bolt

Location

Loc Qty

Loc Code

ST357

486

116191

7

116669

179

116786

300

Purchased

No

250

Each

1,030.000

2 20

MS21042L5



Nut

Location

Loc Qty

Loc Code

ST139

26

114813

26

ST300

1004

115594

308

116105

496

116548

200

Purchased

No

250

Each

5,182.000

8 80

MS21042L4



Nut

Location

Loc Qty

Loc Code

ST300

5182

1123143

2

115589

10

115621

20

116188

3150

116823

2000

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Page 7

Wednesday, February 23, 2011 8:07:31 AM

Work Order ID: 66622



Parent Item: D350-591-312



Parent Item Name: Heli-Access-Step, Long RH

Start Date: 2/23/2011

Required Date: 3/18/2011

Start Qty: 10.00

Required Qty: 10.00

AN960JD10

NAS1149D0363J

Purchased

No

250

Each

24.0000

4 40



Washer



1116583

al3 hel

Location

Loc Qty

Loc Code

ST

6

107715

6

ST335

18

105792

2

112279

16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>GP</i>	DRAWN BY <i>B</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>H</i>	DRAWING NO. D3272	REV. B SHEET 1 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE NTS
A	04.03.01	NEW ISSUE	
B	07.05.18	D3272-1 WAS D2622-120	

RELEASED

07 06 04 *H*

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	X	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET

△
B

GENERAL NOTES:

- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *46622*

11-02-23

Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED <i>CE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272
DATE 07.05.18	TITLE STEP ASSEMBLY, HI LONG	REV. B SHEET 2 OF 3
	SCALE 1:20	



D3272-041 STEP ASSEMBLY (LH. SHOWN)
D3272-042 STEP ASSEMBLY (RH, OPPOSITE)



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN <i>GP</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>LE</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE 07.05.18		TITLE STEP ASSEMBLY, HI LONG	SCALE 1:20


RELEASED

07.06.04 *[Signature]*



B D3272-1 STEP
(MAKE FROM D2622-120 STEP EXTRUSION)

Handwritten note: 100mm



DRILL $\phi 0.128$ (#30) FROM JIG ON BOTH SIDES OF D3272-1 EXTRUSION TO MATCH D3065-041 HOLE PATTERN

DETAIL C
(SCALE 1:5)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Qty -211	Qty -212	Qty -213	Qty -214	Qty -215	Qty -216	Qty -311	Qty -312	Part Number	Description
X							1	D350-591-211	Heli-Access-Step™, Long Step – High Skid, LH
	X						1	D350-591-212	Heli-Access-Step™, Long Step – High Skid, RH
		X					1	D350-591-213	Heli-Access-Step™, Short Step – High Skid, LH
			X					D350-591-214	Heli-Access-Step™, Short Step – High Skid, RH
				X				D350-591-215	Heli-Access-Step™, Short Step – Low Skid, LH
					X			D350-591-216	Heli-Access-Step™, Short Step – Low Skid, RH
						X		D350-591-311	Heli-Access-Step™, Long Step – High Skid, LH
							X	D350-591-312	Heli-Access-Step™, Long Step – High Skid, RH
1								D3070-041	STEP ASSEMBLY (HIGH-LONG, LH)
	1							D3070-042	STEP ASSEMBLY (HIGH-LONG, RH)
		1						D3078-041	STEP ASSEMBLY (HIGH-SHORT, LH)
			1					D3078-042	STEP ASSEMBLY (HIGH-SHORT, RH)
				1				D3168-041	STEP ASSEMBLY (LOW-SHORT, LH)
					1			D3168-042	STEP ASSEMBLY (LOW-SHORT, RH)
						1		D3272-041	STEP ASSEMBLY (HIGH-LONG, LH)
							1	D3272-042	STEP ASSEMBLY (HIGH-LONG, RH)
4	4							D2182B035	RUBBER CUSHION
		2	2	2	2			D2230-1	MOUNTING LUG
		2	2	2	2	4	4	D2230-3	MOUNTING LUG
8	8							D2274	RADIUS BLOCK
						2	2	D2618	BUSHING
4	4	4	4	4	4			D2732-030	CUSHION
2	2	1	1	1	1	2	2	D2856-400-720	ABRASION STRIP
2	2							D3064-1	CLAMP
1	1							D3079-041	SUPPORT ASSEMBLY
4	4							D3080-1	CLAMP
						2	2	D3235-1	MOUNTING LUG
						1	1	D3278-041	SUPPORT ASSEMBLY
2	2	2	2	2	2	2	2	AN3-35A	BOLT
10	10	2	2	2	2			AN4-11A	BOLT
		4	4	4	4	8	8	AN4-13A	BOLT
						2	2	AN5-36A	BOLT
4	4	4	4	4	4	4	4	AN960JD10	WASHER
20	20	12	12	12	12	16	16	AN960JD416	WASHER
						4	4	AN960JD516	WASHER
2	2	2	2	2	2	2	2	MS21042L3	NUT
10	10	6	6	6	6	8	8	MS21042L4	NUT
						2	2	MS21042L5	NUT
						1	1	*DSI 9410-011	STEP MODIFICATION KIT

*DSI 9410-011 Step Modification Kits are provided with all D350-591-311 and D350-591-312 Steps. This kit is provided as an option for the installer and is therefore **NOT REQUIRED** to complete the installation of the D350-591-311 or D350-591-312 Steps. Refer to Figure 21 for installation of the DSI 9410-011 Kit.

